SLEIPNER
*Ocean born. Tech bred.*

# Product Guide

## *How to prepare your vessel for Sleipner's eVision Thrusters*

**SLEIPNER MOTOR AS**
P.O. Box 519
N-1612 Fredrikstad
Norway
www.sleipnergroup.com

**DOCUMENT ID: 7317**
**REVISION: 3**
**DATE: 2022**

**LANGUAGE: EN**

# Important information regarding installation of eVision Thruster Motors

MC_0587

This document contains important information for installation of eVision Thruster Motors.
These instructions must also be followed when upgrading from existing thruster systems to eVision Thruster Motors.
Always follow the installation manual when installing eVision Thruster Motors.

- **eVision Thruster Motor**
  eVision Thruster Motor must be upgraded to firmware version V1.015 or newer.
  eVision Thruster Motors shipped before November 28. 2022 needs to be upgraded.

- **Joystick Panels**
  Control panel PJC2xx must be upgraded to firmware version V3.018 or newer.
  Control panel PJC2xx with hardware V2.000 or older will not support eVision Thruster Motors. Sleipner stopped the production of PJC2xx with HW version V2.000 in Q2 2020. Note that no mechanical modifications are required to replace older PJC2xx panels with PJC2xx HW version V3.000 or newer. Hardware version can be found in the panel info menu or using S-Link programmer. From HW version V3.000, the version is printed on the serial number label.

  Control panel PJC42x must be upgraded to firmware version V1.002 or newer.

  Control panel PJC3xx will not support eVision Thruster Motors.

- **Retractable eVision Thruster Motor**
  Retract controller SR150000 must be upgraded to firmware version V1.036 or newer.
  Function must be configured to “ERV/ERL” on both SR150000 and eVision Thruster Motor.

  Retract controller SR 6 1242 will not support eVision Thruster Motors.

- **AMS**
  Automatic Main Switch works with eVision Thruster Motor without additional firmware update. But an upgrade to the latest firmware is always recommended.

- **GW-1**
  GW-1 must be upgraded to firmware version V1.025 or newer.

- **ESI-1**
  ESI-1 works with eVision Thruster Motor without additional firmware update. But an upgrade to the latest firmware is always recommended.

- **8730B & 8730S**
  8730 works with eVision Thruster Motor without additional firmware update. But an upgrade to the latest firmware is always recommended.

- **RCRS-2**
  S-link remote controller works with eVision Thruster Motor without additional firmware update. But an upgrade to the latest firmware is always recommended.

**© Sleipner Group,** All rights reserved
The information given in the document was right at the time it was published. However, Sleipner Group cannot accept liability for any inaccuracies or omissions it may contain. Continuous product improvement may change the product specifications without notice. Therefore, Sleipner Group cannot accept liability for any possible differences between product and document.

**Register your product and learn more at www.sleipnergroup.com**

SLEIPNER
*Ocean born. Tech bred.*

**SLEIPNER GROUP**
P.O. Box 519
N-1612 Fredrikstad
Norway
www.sleipnergroup.com

Made in Norway

MC_0030