

Dated: 13.09.2019

Description:	Upgrading Motor Only with both flexible coupler and share pin.
Effective date:	October 1st 2019

	Side-Power Product:	Part #
Affected Products:	Electric motor compl SE30SI	2 0101 12
	Electric motor compl SE30-IP	2 0103 12
	Electric motor compl SE30SI-IP	2 0104 12
	Electric motor compl SEP30	2 0107 12
	Electric motor compl SP40S	3 0101 12
	Electric motor compl SE40S2I-IP	3 0104 12
	Electric motor compl SEP40	3 0105 12
	Electric motor compl SEP40-IP	3 0106 12
	Electric motor compl SE60-12V	4 0101 12
	Electric motor compl SE60-12V-IP	4 0104 12
	Electric motor compl SEP60-12V	4 0105 12
	Electric motor compl SE60-24V	4 0101 24
	Electric motor compl SE60-24V-IP	4 0104 24
	Electric motor compl SEP60-24V	4 0105 24
	Electric motor compl SEP60-12V-IP	4 0107 12
	Electric motor compl SEP60-24V-IP	4 0107 24

When changing to S2 version on these thrusters, we introduced a flexible coupler and a new motor bracket. To ensure that a replacement motor (Motor Only) can be used on both S2 and S models, we introduce the Motor Only option with both a flexible coupler and a share pin (used on the S version). An instruction will follow with all Motor Only models – see table above.